

**BID TABULATION FOR BID #5464
WELDING REPAIRS & UPGRADES TO TRASH TRAILERS**

	ARC CONTROL	MASTER MARINE
44161	\$10,554.00	\$6,760.00
49922	\$9,491.00	\$7,020.00
44260	\$10,941.00	\$6,760.00
38765	\$10,299.00	\$6,760.00
53359	\$4,417.00	\$4,940.00
49925	\$3,917.00	\$4,940.00
59958	\$9,356.00	\$6,760.00
49924	\$9,386.00	\$8,190.00
44159	\$10,554.00	\$6,760.00
53161	\$10,586.00	\$7,020.00
44468	\$11,946.00	\$7,020.00
68767	\$10,791.00	\$6,760.00
44174	\$12,021.00	\$8,190.00
44469	\$5,647.00	\$7,020.00
44172	\$9,911.00	\$8,190.00
44169	\$13,876.00	\$7,020.00
44499	\$14,806.00	\$8,190.00
44175	\$11,946.00	\$8,190.00
44767	\$9,886.00	\$7,020.00
44176	\$10,361.00	\$8,190.00
38106	\$2,649.00	\$2,405.00
44887	\$12,021.00	\$7,120.00
53360	\$8,881.00	\$7,050.00
44467	\$12,021.00	\$7,150.00
44461	\$12,021.00	\$7,150.00
44751	\$12,021.00	\$7,150.00
44500	\$12,021.00	\$7,150.00
44173	\$10,854.00	\$7,150.00
38771	\$4,862.00	\$3,445.00
44170	\$12,246.00	\$8,190.00
TOTAL	\$300,289.00	\$205,660.00
TIME TO REPAIR	5 days	3-5 days

DOOR REPAIR	\$2,459.00	\$3,651.00
DOOR LATCH	\$830.00	\$895.00
DOOR HINGES	\$1,930.00	\$690.00
FRONT BASKET	\$1,467.00	\$1,315.00
REPAIR SIDE FRONT BOTTOM	\$2,860.00	\$2,005.00
REPAIR REAR UPRIGHT	\$1,350.00	\$625.00
MOVE LIGHT HOLD MOUNT	\$255.00	\$160.00
SIDE ANGLES REMOVED	\$1,500.00	\$243.00

SIDE ROPE TIE DOWN BOTH SIDES	\$1,170.00	\$625.00
SIDE ROPE TIE DOWN 1 SIDE ONLY	\$585.00	\$313.00
FLOOR METAL REPLACEMENT (sq ft)	\$48.00	\$383.00
FRONT OR SIDE METAL REPAIR (sq ft)	\$60.00	\$103.00
REPLACE FLOOR (sq ft)	\$48.00	\$103.00
ANGLE REPAIR (sq ft)	\$190.00	\$103.00
REPLACE UPPER 2 FEET UPRIGHT REAR LIGHT (per side)	\$900.00	\$243.00
RUST REMOVAL (sq foot)	\$30.00	\$70.00
REPAIR TOP OF TRAILER TOP CHANNEL (linear ft)	\$180.00	\$173.00
STRAIGHTEN HYDRAULIC HOSE HOLDER	\$75.00	\$70.00
REMOVE TRAILER STAND	\$75.00	\$70.00
ADD HYDRAULIC LINE HOLDER	\$150.00	\$173.00