

# BID TABULATION FOR BID #5747

ENGINE REPLACEMENT ON ELGIN PELICAN SWEEPER

DS DIESEL SERVICES	SUNSOUTH
\$29,827.27	\$37,575.00
30 DAYS TO REPAIR	6-8 WEEKS TO REPAIR